# **Notice**



**SEPTEMBER / 27 / 2010** 

Please add this notion	REVISION 0	_	
☐ CORRECTION ☐ SERVICE FLASH	<ul><li>▶ PRODUCTION CHANGE</li><li>■ ADD INFORMATION</li></ul>	FILE NO.	
		11111	

Category:

LCD55L4 Effective from : Chassis No. P55L4-00 Model:

Destination: U.S.A. / CANADA REF : No. SM780176-01

**COLOR TELEVISION** 

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. DP55360-00. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P55360-00 used in Model DP55360 (SM780176).

## SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

### 1. IN THE SERVICE ADJUSTMENTS

#### PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be 2Ah in the table and in Note 2.

## 2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

E : Add as a possible sub D: Design F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 23, Chassis Electrical Parts List	A100	Old	1AA0B10N28700	ASSY,PWB,MAIN N8TE	1	NO	D
		New	1AA0B10N287A0	ASSY,PWB,MAIN N8TF	1	NO	
Page 16, Chassis Electrical Parts List	IC5800 -	Old	QXXAAJQ1245	IC TC58NVG0S3ETA00	1	NO	D
		New	QXXAAJQ1284	IC TC58NVG0S3ETA00 N8TF	1	NO	
Page 15, Chassis Electrical Parts List	IC800	Old	QXXAAJQ1240	IC LC87F2932AVU-Y10US1T	1	NO	. D
		New	QXXAAJQ1278	IC LC87F2932AVU-N8TF	1	NO	

Sanyo Manufacturing Corporation 2010

© Sanyo Manufacturing Corporation 2010

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

September 2010 SMC

Published in Mexico